

## BL-1718

Turning discs on the vehicle is the recommended method of using the device, as it provides significantly better results due to proper centering of the disc. It greatly reduces the risk of the disc becoming unbalanced after the repair.



## Technical Data

|                     |                         |
|---------------------|-------------------------|
| Disc thickness      | 39 mm                   |
| Indication accuracy | $\leq 0.002 - 0.005$ mm |
| Feed                | 8.5 mm/min.             |
| Measuring speed     | 98 obr./min.            |







